



16 Commerce Blvd., Middleboro, MA 02346

Recall Notice
October 16th, 2023

Gerson G71 P100 OV Cartridge

Relevant Part Numbers: 0871571, 08G71FP, 08G71WU

Dear Valued Customer,

Please read this document in its entirety. Please also share this document with anyone who may be affected, such as someone to whom you sold the in-scope products.

During recent evaluations, Gerson has determined that some of the model #G71 OV-P100 Cartridges were manufactured using filters that were defective, which may impact the overall performance of the cartridge in protecting users from particulates. In follow up testing completed by Gerson, limited quantities within the impacted lots were found not to meet the NIOSH minimum efficiency level of 99.97% or 0.03% maximum penetration with DOP.

The products under recall were produced between 11/22/2021 (M10871571NK22A) and 11/23/2021 (M10871571NK23A).

Product Description	Gerson ID	Affected FG Lots (Shipping Label)	Contains (Cartridge Lot)
GERSON G71 CART OV 2 PK	0871571	M10871571NK23A	M10871571NK23A
GERSON G71 CART OV 2 PK	0871571	M10871571NK22A	M10871571NK22A
FASTENAL G71 CART OV 2 PK	08G71FP	D008G71FPO082A	M10871571NK22A M10871571NK23A
FASTENAL G71 CART OV 2 PK	08G71FP	D008G71FPO194A	M10871571NK23A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUO171A	M10871571NK22A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUO290A	M10871571NK23A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUP065A	M10871571NK22A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUP086A	M10871571NK22A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUP115A	M10871571NK22A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUP214A	M10871571NK22A
WURTH G71 CART OV 2 PK	08G71WU	D008G71WUP234A	M10871571NK22A

Please review your product inventory; if you have any of these products from the specific lot codes listed above, please contact Gerson at 1-508-947-4000 for return and replacement information.

- See Images 1, 2, and 3 below for the location of the lot code on the box/shipping labels.
- See Image 4 below for the location of the lot code on the cartridge packaging/bags.
- See Image 5 below for the location of the lot code on the individual cartridge labels.
- Please note: The lot code on the bags and individual cartridges should match, however, the lot code present on the box may differ, so it is important to check all three locations for all affected lots.

We believe we have corrected the issue at our production facility and are working diligently to prevent recurrence of such an issue in the future. Please note that this recall is only for the products and lot numbers listed above and does not affect any other Gerson cartridges, filters, or respirators.

We sincerely apologize for any inconvenience this may cause and appreciate your continued patience. Should you have any questions please contact your local Sales Representative or Client Services at 1-508-947-4000.



Image 1




Image 2



Image 3



Image 4




Image 5